



OUT OF PROVINCE JOURNEYMEN

GUIDELINES

The checklist on the right shows the steps that Journeymen from outside of British Columbia need to follow, depending on whether or not they have passed their Inter Provincial Examination.

EMPLOYER RESPONSIBILITIES

- Register Journeymen with the IBEW 258
- Ensure Journeymen have logged 450 Liveline hours
- Coordinate PSSP Category 2, 3 and 5 training as applicable as well as Limits of Approach training

Journeymen can contact the Joint Line Apprenticeship & Trades Training Committee office at 604-533-2722 to arrange to take an IP refresher course as well as a Liveline course with the Electrical Industry Training Institute (EITI).

Journeymen with NO IP or Red Seal

- ✓ Register with the IBEW 258 Union
- ✓ Fill out the Application to Challenge the IP Exam from the ITA and send it in (leave Reg # blank)

Journeymen with the IP or Red Seal

- ✓ Register with the IBEW 258 Union

IN ADDITION, THE FOLLOWING ARE ALSO REQUIRED TO BE ALE TO WORK ON BC HYDRO SYSTEMS

- ✓ Liveline Training at (EITI)
- ✓ Proof of 450 logged Liveline hours (a minimum must be 300 hours in LL3 Phase)
 - ✓ Limits of Approach Training
- ✓ PSSP Categories (2) & (3) are mandatory, while PSSP Category (5) authorizes rights to SPG's and Liveline Permits

(To be authorized to BC Hydro PSSP Category (5), you must provide proof of an IP Certificate and proof of 450 Liveline hours)