



OUT OF PROVINCE JOURNEYMEN

The checklist on the right shows the steps that Journeymen from outside of British Columbia need to follow, depending on whether or not they have passed their Inter Provincial Examination.

GUIDELINES

EMPLOYER RESPONSIBILITIES

- Register Journeymen with the IBEW 258
- Ensure Journeymen have logged 500 live line hours
- Coordinate PSSP Category 2, 3 and 5 training as applicable as well as Limits of Approach training

Journeymen with NO IP or Red Seal

- ✓ Register with the IBEW 258 Union
- ✓ Fill out the Application to Challenge the IP Exam from the ITA and send it in (leave Reg # blank)

Journeymen with the IP or Red Seal

- ✓ Register with the IBEW 258 Union

IN ADDITION, THE FOLLOWING ARE ALSO REQUIRED TO BE ABLE TO WORK ON BC HYDRO SYSTEMS

- ✓ Live line Training at (EITI)
- ✓ Proof of 500 logged live line hours (a minimum must be 300 hours in LL3 Phase)
 - ✓ Limits of Approach Training
- ✓ PSSP Categories (2) & (3) are mandatory, while PSSP Category (5) authorizes rights to SPG's and live line permits

(To be authorized to BC Hydro PSSP Category (5), you must provide proof of an IP Certificate and proof of 500 live line hours)

Journeymen can contact the Joint Line Apprenticeship & Trades Training Committee office at 604-533-2722 to arrange to take an IP refresher course as well as a live line course with the Electrical Industry Training Institute (EITI).